

General Environmental Incident Summary

Incident: 3439 **Date/Time Notice:** 8/29/2014 13:45 **DEM Incident No:**

Responsible Party: Von Johnson

Date Incident: 8/25/2014 **Time Incident:** 0601 **Duration:**

County: Williams **Twp:** 154 **Rng:** 101 **Sec:** 2 **Qtr:**

Lat: 48.18347 **Long:** -103.62570 **Method:** Address matching

Location Description: The Fuel Stop located at 4201 2nd Ave., W, Williston

Submitted By: Crystal Cummie

Affiliation: Supervisor for Racers

Address: 450 NewPort Center Dr

Suite 480

City: Newport Beach

State: CA

Zip: 92660

Received By: Brad Torgerson

NDDH

Contact Person: Von Johnson

12772 29th St., SW

Belfield, ND 58622

Distance Nearest Occupied Building: 50 Feet

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 50.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Truck backed over fuel pump at pump island. Fuel ran across asphalt apron area to the east approximately 70 feet ten south along frontage road 210 feet. Some asphalt had been removed from the frontage road.

Risk Evaluation:

no

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

diesel impacts to soil along the frontage road.

Action Taken or Planned:

The Williston Fire Dept. and City of Williston personnel (Jim - Ph- 770-2830) dumped sand on the released fuel.

Wastes Disposal Location: Six Pioneers personnel (Shawn Stubbs - Ph. - 406-548-5498) cleaned-up the impacted sand and transported for disposal at an unknown location.

Agencies Involved: Williston Fire Dept.

Updates

Date: 12/18/2014 **Status:** Inspected; More Followup Required **Author:** Cooper, Mike

Updated Volume:

Notes:

According to the incident summary, this spill impacted the surrounding location. Arrival on site at 11:12 am, Temperature 26 F, Wind 5-10mph North. Site clean up was apparent around the diesel pump islands. Remnants of sand were still available on site. Pictures Taken. Significant staining around pump islands is apparent due to frequent use since incident. A new construction project has commenced on the east side of the frontage road. No impacted soil was noticed from the spill in question, although there is still a large amount of staining on the concrete leading up to the frontage road. Further Followup is required to check for vegetative growth in ditch once new construction project has ceased.